



June 16, 2022

Project No. GL2040906204

Jerry Wick, MC-127

Texas Commission on Environmental Quality
P.O. Box 13087
Austin, TX 78711-3087

NOTIFICATION OF PLUGGING AND ABANDONMENT OF MW-44 AT FRISCO COMMUNITY DEVELOPMENT SITE (FORMER EXIDE FRISCO); RN100218643; CN605857168

Dear Mr. Wick:

Golder Associates USA Inc. (Golder), a member of WSP, on behalf of the Frisco Community Development Corporation (Frisco CDC), is submitting this notification to the Texas Commission on Environmental Quality (TCEQ) regarding the plugging and abandonment of monitoring well MW-44 at the Frisco Community Development Site located at 7471 Old 5th Street, Frisco, Texas (Site).


During a recent rain event, debris carried by flood waters of Stewart Creek dislodged the concrete surface seal of MW-44 and pulled the well's polyvinyl chloride (PVC) casing and screen up from the original depth where the well was set. MW-44 was installed by Golder during the Affected Property Assessment Report (APAR) investigation in January 2014 and is not currently used as part of a groundwater monitoring program at the Site. In email correspondence between Golder and the TCEQ on May 23, 2022, the TCEQ concurred the best course of action would be to plug and abandon MW-44 and install a replacement well during implementation of the Response Action Plan (currently pending approval from the TCEQ as part of the overall Resource Recovery and Conservation Act [RCRA] permit modification for the Site).

On May 26, 2022, Golder mobilized to the Site with Sunbelt Industrial Services (Sunbelt) to plug and abandon MW-44. Sunbelt removed 10 feet of PVC screen and 9 feet of PVC casing and riser pipe, backfilled the well hole with 2 bags of 3/8-inch bentonite chips and cemented the top 3 feet. A copy of the State of Texas Well Report (#351730) and the State of Texas Well Plugging Report (#219437) for MW-44 is attached as Attachment A.


Please address the undersigned with any questions or comments you may have.

Sincerely,

Golder Associates USA Inc.



Emily P. Forthaus
Senior Consultant



Todd H. Rees
Senior Program Leader

EPF/THR

CC: Mack Borchardt, Frisco Community Development Corporation
Brad Weaver, City of Frisco

Attachments: Attachment A – State Well Reports

ATTACHMENT A
STATE WELL REPORTS

STATE OF TEXAS WELL REPORT for Tracking #351730

Owner: Exide	Owner Well #: MW 44
Address: 7471 5th Ave Frisco, TX	Grid #: 18-50-8
Well Location: 7471 5th Ave Frisco, TX	Latitude: 33° 08' 37" N
Well County: Collin	Longitude: 096° 49' 42" W
	Elevation: No Data
Type of Work: New Well	
	Proposed Use: Monitor

Drilling Start Date: **1/7/2014** Drilling End Date: **1/14/2014**

	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
Borehole:	7	0	15

Drilling Method: **Hollow Stem Auger**

Borehole Completion: **20/40 Sand**

	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
Annular Seal Data:	0	2	2 Cement
	2	3	2 Bentonite
	3	15	5 Sand

Seal Method: **Mix**

Sealed By: **Driller**

Distance to Property Line (ft.): **No Data**

Distance to Septic Field or other concentrated contamination (ft.): **No Data**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **No Data**

Surface Completion: **Surface Slab Installed**

Water Level: **No Data**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **No Test Data Specified**

Water Quality:	<i>Strata Depth (ft.)</i>	<i>Water Type</i>
	No Data	No Data

Chemical Analysis Made: **Unknown**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Strata Core Services, LLC**
5070 Brush Creek Road
Fort Worth, TX 76119

Driller Name: **Dan Spaust** License Number: **3038**

Comments: **No Data**

Lithology:
 DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
 BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	15	Clay

<i>Dia. (in.)</i>	<i>New/Used</i>	<i>Type</i>	<i>Setting From/To (ft.)</i>
2"	New	PVC Screen	15' to 5' .010
2"	New	PVC Riser	5' to 0 s40

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540

