

EXHIBIT “6”



LEGEND

- FORMER OPERATING PLANT BOUNDARY
- - - UNDEVELOPED BUFFERED PROPERTY BOUNDARY
- - - FORMER PATH OF NORTH-TERRITORY (1981 AERIAL PHOTO)
- - - FORMER PATH OF WEST-TERRITORY (1977 AERIAL PHOTO)
- - - FORMER PATH OF STORM WATER (1981 AERIAL PHOTO)
- EXISTING MONITORING WELL
- SOIL BURNING MONITORING WELL
- POLYMER ENCLOSURE AREA (LEAD POLYMER ACTION LEVEL = 200 mg/kg)
- POLYMER ENCLOSURE AREA (LEAD POLYMER ACTION LEVEL = 200 mg/kg)
- AREAS THAT WILL BE CAPPED
- PROPOSED SLURRY WALL LOCATIONS



NOTES:
 1. POLYMER ENCLOSURE MONITORING CONCENTRATION LEVEL.
 2. POLYMER ENCLOSURE MONITORING CONCENTRATION LEVEL.
 POLYMER ENCLOSURE MONITORING CONCENTRATION LEVEL.
 POLYMER ENCLOSURE MONITORING CONCENTRATION LEVEL.

SOURCE: PASTOR, BEHLING & WHEELER, LLC

REV.	DATE	DESCRIPTION	DR BY	APP BY

GICOOK-JOYCE INC.
 ENGINEERING AND CONSULTING
 812 WEST JUSTICE AVENUE, SUITE 200
 FORT WORTH, TEXAS 76102
 TEXAS REGISTERED ENGINEERING FIRM F-883

PROJECT:
 EXIDE FACILITY & ADJACENT PROPERTIES
 FRISCO, TEXAS

SHEET TITLE:
 EXHIBIT 6
 CLOSE IN PLACE REMEDIATION PLAN

DES BY: JDB
 PROJECT NO: 12081.01
 DATE ISSUED: 07-17-2013
 SHEET NO. 1 OF 1
 SHEETS 1 OF 1
 PURPOSE: NA